



## NEDMAG SITE ACCESS REQUIREMENTS FOR DRIVERS

### General

- On arrival at Nedmag, drivers must provide at the porter's lodge documentation with:
  - Nedmag order number
  - Product name
  - Place to load/unload
- Drivers' identification papers may be requested

### Safety

- Personal Protective Equipment (PPE) to be worn on the Nedmag site, to be provided by the driver:
  - Safety helmet
  - Safety shoes
  - Safety glasses with side protection (or chemical goggles)
  - Clothing: arms, legs and body covered
  - Gloves, fit for purpose
  - Additional PPE:
    - as mentioned in the transport emergency card (Tremcard) are mandatory
    - as supplied by the transport company have to be used
    - other PPE can be made mandatory by contract
- No loading will take place if it is apparent that the driver is:
  - Under the influence of alcohol, medicines or drugs
  - Noticeably fatigued

### Codes for safe and responsible behaviour

#### Obligations:

- Follow instructions of Nedmag personnel
- Respect the site procedures and warning signs
- Request permission prior to entering plants and prior to conducting activities
- Respect maximum speed limits
- Respect traffic signs
- Follow indicated routes
- Prevent spills
- In case of spills or other incidents, report immediately to Nedmag contact man
- After loading caustic magnesia, close shutters before driving to the weighbridge
- Park only where allowed and switch of the engine
- Keep the working area clean and accessible

#### Prohibitions:

- Possession or use of alcohol, drugs or weapons
- Criminal activities, such as theft
- Smoking during loading
- Use of cameras, videos etc.
- Unauthorized passengers or animals

*P 2.12 Date of issue: May 2011*